

GLARE SHIELD AND INSTALLATION

- Position shield on housing as shown in Figure 2 and mark drilling locations through slotted holes in shield. (See Figure 1).

- Remove shield and drill 1/2" dia. holes through housing (4 places).

- Insert well-nut into each hole.

- Position and install glare shield using 1/4-20 screws and flat/lock washers.

- Tighten screws until snug.

- NOTE: Glare shield should be placed on side that will best block light from the area to be shielded, and that will allow maximum reflector performance. (See Figure 3).

FIGURE 1






FIGURE 2

SHIELD POSITIONING




Edge of shield even with edge of Lens opening TYPE II




Edge of shield even with edge of Lens opening TYPE III AND FORWARD THROW


FIGURE 3



TYPE II



TYPE III



TYPE FA/FP

Figure 3 drawings show location of shields for best performance of reflector. Whenever possible, glare shields should be placed in the indicated positions. (See Shaded areas)

WLS LIGHTING SYSTEMS

P. O. BOX 100519
 FORT WORTH, TX 76185
 800.633.8711
 Fax-817.735.4824
www.wslighting.com